




MARKING B, C



C19

H 3/4



D35

H 2

2



PE14




PE18

1




D48

FILM



C8



C19

C18

MARKING B, C



C18

H 3/4



D35

H 2

2



D37

H 2

2



D37

H 2

2




D37

H 2

2

⊕



D37



H 2

2

D37

H 2

2



D10

H 3/8

3/8

D24

H 3/8

3/8

D32

H 3/8

3/8

D31

H 3/8

3/8

D23

H 3/8

3/8